



UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 6,929,781B1

Serial No. : 09/856,661

Filed : November 17, 1999

Issued : August 16, 2005

For : INTERCONNECTION SUPPORT FOR PLATE-LIKE MICROCOMPONENTS

Certificate
FEB 06 2006
of Correction

**PETITION FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323**

Assistant Commissioner for Patents
Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

The mistake(s) was/were incurred through the fault of the Patent and Trademark Office and is/are clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

At least some of the mistakes were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) do not constitute new matter or require reexamination.

02/02/2006 SZEWDIE1 00000006 09856661

01 FC:1811

100.00 0P

Void date: 02/02/2006 SZEWDIE1

02/02/2006 SZEWDIE1 00000006 09856661

01 FC:1811 -100.00 0P

02/02/2006 SZEWDIE1 00000008 6929781

01 FC:1811

100.00 0P

FEB 6 2006

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,



John R. Moses, Reg. No. 24,983
Attorney for Applicants

MILLEN, WHITE, ZELANO
& BRANIGAN, P.C.
Arlington Courthouse Plaza I
2200 Clarendon Blvd. Suite 1400
Arlington, Virginia 22201
Telephone: (703) 243-6333
Facsimile: (703) 243-6410

Attorney Docket No.: MERCK-2245

Date: February 1, 2006

JRM:at

FFB 6/2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,929,781B1

DATED : August 16, 2005

INVENTOR(S) : Michael HOHMANN et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 3, line 51, reads "connections 10" should read -- connections (10) --
Column 3, line 66, reads "fluid line 10b" should read -- fluid line (10b) --
Column 3, line 67, reads "hole 10" should read -- hole (10) --
Column 4, line 44, reads "plane parallel" should read -- plane-parallel --
Column 4, line 60, reads "has a substantially" should read -- has substantially --
Column 5, line 8, reads "hole 10" should read -- hole (10) --
Column 5, line 11, reads "connection 11" should read -- connection (11) --
Column 5, line 23, reads "side wall 9" should read -- side wall (9) --

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan P.C 2200
Clarendon Boulevard Suite 1400
Arlington, VA 22201

PATENT NO. 6,929,781



No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

FEB 6 2006